



August 1, 2013

Per July 24, 2013 email information request from the Ohio Environmental Protection Agency, Heritage Thermal Services (HTS) is providing the following documents for your review:

1. 7-13-13 Incident Release – Summary of Post Incident Events
2. Work Plan to Evaluate the Extent of the Ash Release at Heritage Thermal Services East Liverpool, Ohio dated July 24, 2013
3. Certificate Of Analysis
 - a. Lab ID W376973 (10 pages)
 - b. Lab ID W377841 (7 pages)
 - c. Lab ID W378797 (7 pages)
 - d. Lab ID W379578 (7 pages)
 - e. Lab ID W380441 (10 pages)
 - f. Lab ID W381244 (7 pages)
4. HTS 7-13-13 Incident Analytical Results table (3 pages, double-sided)
5. HTS 7-13-13 Incident Analysis Results table (1 page, 5 sample lines)
6. Certificate of Analysis for all samples listed in the two above-mentioned tables
7. SW-846 Method 6010 ICV I / CCV I Report
8. Certificate Of Analysis for SW-846 Method 6010 ICV I / CCV I Report

Please forward questions to me at cberinger@heritage-thermal.com. Heritage Thermal Services trusts that this latest information satisfies the request by the Ohio Environmental Protection Agency .

Sincerely,

A handwritten signature in blue ink that reads "Carrie L. Beringer". The signature is fluid and cursive, with the first name "Carrie" being more prominent.

Carrie L. Beringer
Heritage Thermal Services, Inc.
Environmental, Health, & safety Manager